

MAY 17 2018



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D119-646-012

Job Sheet 177604



Part No: D119-646-012

Job Qty: 1 ea

Part Name: AW119 Skidtube with Wearpads - RH



JUN 01 2018

Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 5/15/18

Job Tracking No:

Due Date: 6/5/18

Created By: Michelle Gagnon-Donovan

Type: Stock

Description:

Note: DWG REV D IPP RevA: New issue DD verified by:EC IPP REV:B 12.11.05 raise to chg002 (ECN 12-675) DD
verf:JLM IPP REV:C 13.03.20 raise to chg003 (ECN 13-534) DD verf:JLM IPP REV:D 14.11.25 IIN REV:C
(ECN 14-628) DD verf:JLM IPP REV:E 17.05.11 AS PER IIN REV.D DD verf:JFS

Ship Via:

Chgect 21
9-50

Reattachement

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	6/5/18	6/5/18	0.00	0.00	Start Up Stores/Pkg-1		JUN 01 2018
110	Packaging	1 pcs	6/5/18	6/5/18	0.00	0.00	Packaging1-1		
120	QC	1 pcs	6/5/18	6/5/18	0.00	0.00	QC4		
125	DC	1 pcs	6/5/18	6/5/18	0.00	0.00	DC		
130	Packaging	1 pcs	6/5/18	6/5/18	0.00	0.00	Packaging3-1		
140	QC21-FG	1 Ea	6/5/18	6/5/18	0.00	0.00	QC21		21 180013

Part Op 125 - Photocopy bluefile & type labels per PPP D119-646-012
Descriptions: 130 - Identify and pack for shipping as per PPP D119-646-012

F9074

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
AN3C50A	Bolt	8 Ea (8 ea)	110-Packaging	5019395
AN4C6A	Bolt	12 Ea (12 ea)	110-Packaging	5057515
D119-646-041	AW119 Replacement Skidtube with Wearpads - Fits LH or RH	1 Ea (1 ea)	110-Packaging	5059578
D119-646-311	Ground Handling	1 Ea (1 ea)	110-Packaging	5072078
D2652	Bushing	16 Ea (16 ea)	110-Packaging	5054604
D2712	Set Screw	12 Ea (12 ea)	110-Packaging	5031303
D3407-041	Tow Ring	1 Ea (1 ea)	110-Packaging	5058326
D3417-5	Washer	2 Ea (2 ea)	110-Packaging	5077284
D3456-1	Washer	1 Ea (1 ea)	110-Packaging	5057206
D3672-3	Washer, Phenolic	24 Ea (24 ea)	110-Packaging	5027022
D3672-7	Washer, Phenolic	24 Ea (24 ea)	110-Packaging	5044305
D3883-2	Saddle, Outside RH	2 Ea (2 ea)	110-Packaging	5067912
D3884-2	Saddle, Inside RH	2 Ea (2 ea)	110-Packaging	5070391
MS21043-3	Nut	8 Ea (8 ea)	110-Packaging	5034415
MS21043-4	Nut	13 Ea (13 ea)	110-Packaging	5056046
MS21250-05-006	Bolt	8 Ea (8 ea)	110-Packaging	50137074
NAS1149C0332R	Washer	8 Ea (8 ea)	110-Packaging	5049832
NAS1149C0432R	Washer	24 Ea (24 ea)	110-Packaging	5050052
NAS1149C0532R	Washer	8 Ea (8 ea)	110-Packaging	5055851

57412

5059578

Plex 5/15/2018 11 AM Dart Gagnon, Michelle



Container No: S077171



Part: D119-646-012

Job No: 177604

Serial No/Batch: S077171

Revision:

Inspector:

Exp Date: 06/01/2018

Instructions:

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Date: 06/01/18

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
110-Packaging	AN3C50A	8	78	0
	AN4C6A	12	391	0
	D119-646-041	1	12	0
	D119-646-311	1	1	0
	D2652	16	721	0
	D2712	12	797	0
	D3407-041	1	20	0
	D3417-5	2	8	0
	D3456-1	1	77	0
	D3672-3	24	1,164	0
	D3672-7	24	507	0
	D3883-2	2	8	0
	D3884-2	2	14	0
	MS21043-3	8	1,144	0
	MS21043-4	13	965	0
	MS21250-05-006	8	78	0
	NAS1149C0332R	8	5,512	0
	NAS1149C0432R	24	2,335	0
	NAS1149C0532R	8	357	0

Part Specifications

Specifications could not be found.

Plex 5/15/18 10:11 AM Dart.Gagnon.Michelle

6.0 PARTS LIST

6.1 Standard Skidtubes

Item	Qty -011	Qty -012	Qty -111	Qty -112	Qty -211	Qty -212	Qty -041	Qty -141	Qty -151	Qty -241	Qty -251	Qty -311	Part Number	Description
	X												D119-646-011	STANDARD SKIDTUBE INSTALLATION WITH WEARPADS, LH
		X											D119-646-012	STANDARD SKIDTUBE INSTALLATION WITH WEARPADS, RH
			X										D119-646-111	STANDARD SKIDTUBE INSTALLATION WITH FULL LENGTH WEARPLATES & WEARPADS, LH
				X									D119-646-112	STANDARD SKIDTUBE INSTALLATION WITH FULL LENGTH WEARPLATES & WEARPADS, RH
					X								D119-646-211	STANDARD SKIDTUBE INSTALLATION WITH TRAINING WEARPLATES, LH
						X							D119-646-212	STANDARD SKIDTUBE INSTALLATION WITH TRAINING WEARPLATES, RH
	1	1					X						D119-646-041	REPLACEMENT STANDARD SKIDTUBE WITH WEARPADS
			1	1				X					D119-646-141	REPLACEMENT STANDARD SKIDTUBE WITH FULL LENGTH WEARPLATES & WEARPADS
									X				D119-646-151	WEARPLATE KIT STANDARD SKIDTUBE
					1	1				X			D119-646-241	REPLACEMENT STANDARD SKIDTUBE WITH TRAINING WEARPLATES
											X		D119-646-251	TRAINING WEARPLATES STANDARD SKIDTUBE
	1	1	1	1	1	1						X	D119-646-311	GROUND HANDLING KIT
1							1						D3887-041	STANDARD SKIDTUBE ASSY. WITH WEARPAD
20								1					D3887-043	STANDARD SKIDTUBE ASSY. WITH WEARPLATE & WEARPAD
26									1				D3847-043	FWD WEARPLATE ASSY
27									1				D3847-045	CENTER WEARPLATE ASSY
28									1				D3847-047	AFT WEARPLATE ASSY
29									5				D3847-1	WEARPAD
30									1				D3847-11	WEARPAD
31									30				AN3C5A	BOLT
32									30				AN960C10L	WASHER (OR NAS1149C0332R)
40										1			D3887-045	STANDARD SKIDTUBE ASSY. TRAINING WEARPLATE
44											1		D3849-041	FWD TRAINING WEARPLATE ASSY
45											1		D3849-043	AFT TRAINING WEARPLATE ASSY
51											16		D3904-1	WASHER
52											8		AN3C46A	BOLT
53											8		MS21043-3	NUT
60	2		2		2								D3883-1	SADDLE, OUTSIDE, LH
61		2		2		2							D3883-2	SADDLE, OUTSIDE, RH
62	2		2		2								D3884-1	SADDLE, INSIDE, LH
63		2		2		2							D3884-2	SADDLE, INSIDE, RH
64	16	16	16	16	16	16							D2652	BUSHING
65	8	8	8	8	8	8							AN3C50A	BOLT
66	12	12	12	12	12	12							AN4C8A	BOLT
67	8	8	8	8	8	8							MS21250-05006	BOLT
68	8	8	8	8	8	8							AN960C10L	WASHER (OR NAS1149C0332R)
69	24	24	24	24	24	24							AN960C416L	WASHER (OR NAS1149C0432R)
70	8	8	8	8	8	8							AN960C516L	WASHER (OR NAS1149C0532R)

© COPYRIGHT © 2009 BY DART AEROSPACE USA, INC.
 THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED
 OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC

Revision: D
 Date: 17.02.21

Item	Qty -011	Qty -012	Qty -111	Qty -112	Qty -211	Qty -212	Qty -041	Qty -141	Qty -151	Qty -241	Qty -251	Qty -311	Part Number	Description
71	8	8	8	8	8	8							MS21043-3	NUT
72	12	12	12	12	12	12							MS21043-4	NUT
73	12	12	12	12	12	12							D2712	SET SCREW
74	16	16	16	16	16	16							D3672-7	WASHER
75	24	24	24	24	24	24							D3672-3	WASHER
76	8	8	8	8	8	8							D3672-7	WASHER
80	1	1	1	1	1	1							D3407-041	TOW RING
81	2	2	2	2	2	2							D3417-5	WASHER
82	1	1	1	1	1	1							D3456-1	WASHER
83	1	1	1	1	1	1							MS21043-4	NUT
90												2	D3886-041	LUG ASSEMBLY
91												8	D2652	BUSHING
92												4	AN3C46A	BOLT
93												4	AN960C10L	WASHER (OR NAS1149C0332R)
94												4	MS21043-3	NUT
*120													MS21250-05048	BOLT
*121													NAS1149C0532R	WASHER
*122													D3672-7	WASHER
*123													MS21043-5	NUT

* SUPPLIED WITH DART CROSSTUBES

Change Record

PAGE 1 OF 1

Part Number: D119-646-011/-012

Description: STD SKIDTUBE w/ WEARPADS, LH/RH

[illegible]

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Skid-tube ☐</td> <td style="width: 15%;">Cross tube ☐</td> <td style="width: 15%;">Water Jet ☐</td> <td style="width: 15%;">Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																		
Description Work Order Deviation				Disposition				Completed By																	
								Lead hand / Supervisor Approval Verification																	
								QC / QA Coordinator Approval																	
Root Cause		FAULT CATEGORY																							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐																				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐																				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐																				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐																				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐																				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐																				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐																				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐																				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐																				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐																				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____																							
Misidentified ☐	Past Due ☐																								